Agilent No.: 10030339-1

ABSTRACT

[00068] Systems and methods for performing multi-measurements are provided.

One such method includes: displaying a first icon corresponding to a multi-source measurement, displaying waveforms, visually associating the first icon with at least one of the waveforms responsive to user input, and performing a multi-source measurement related to the waveforms.